



FINISH: BRACKET SHALL BE POLYESTER POWDER COAT FINISH IN A STANDARD COLOR.

 <p>P.O. Box 340 Eastpointe, MI 48021 P: (586) 771-4610 F: (586) 771-5527 www.lytepoles.com a DWM company</p>	DRAWN: M. HARVALA	6/8/2015	<p>SOME GEOGRAPHICAL AREAS HAVE SPECIAL WIND CONDITIONS THAT CAN CREATE WIND INDUCED VIBRATIONS CAUSING A FATIGUE PROBLEM. NO METHOD HAS YET BEEN FOUND FOR PREDICTING DESTRUCTIVE LIGHTING POLE VIBRATION. THESE CONDITIONS ARE UNIQUE AND CANNOT BE GUARANTEED AGAINST, AND ARE THE RESPONSIBILITY OF A LOCAL SITE ENGINEER.</p>	 <p>180° 270° ← → 90° 0° HANDHOLE</p>			
	CHECKED				TITLE:		
	REVISION:	DATE:			CATALOG:		
	APPROVED:				DWG NO: PTA-5SQ-T2	SIZE C	SHEET 1 OF 1
	QUOTE:						
	S.O.#						
REF:	SCALE: NONE						